

Preface	xv
1 Introduction	1
1.1 Introduction	1
1.2 Introduction to Control Systems	1
1.3 Definitions	6
1.4 Historical Background	8
1.5 Digital Control Development	12
1.6 Mathematical Background	13
1.7 General Nature of the Engineering Control Problem	15
1.8 Computer Literacy	16
1.9 Outline of Text	16
2 Writing System Equations	19
2.1 Introduction	19
2.2 Electric Circuits and Components	21
2.3 Basic Linear Matrix Algebra	25
2.4 State Concepts	28
2.5 Transfer Function and Block Diagram	34
2.6 Mechanical Translation Systems	35
2.7 Analogous Circuits	41
2.8 Mechanical Rotational Systems	41
2.9 Thermal Systems	46
2.10 Hydraulic Linear Actuator	48
2.11 Liquid-Level System	53
2.12 Rotating Power Amplifiers	54
2.13 DC Servomotor	56
2.14 AC Servomotor	57
2.15 Lagrange's Equation	59
2.16 Summary	63
3 Solution of Differential Equations	64
3.1 Introduction	64
3.2 Standard Inputs to Control Systems	65

3.3	Steady-State Response: Sinusoidal Input	66
3.4	Steady-State Response: Polynomial Input	67
3.5	Transient Response: Classical Method	70
3.6	Definition of Time Constant	73
3.7	Example: Second-Order System—Mechanical	74
3.8	Example: Second-Order System—Electrical	76
3.9	Second-Order Transients	77
3.10	Time-Response Specifications	80
3.11	CAD Accuracy Checks (CADAC)	82
3.12	State-Variable Equations	82
3.13	Characteristic Values	84
3.14	Evaluating the State Transition Matrix	85
3.15	Complete Solution of the State Equation	88
3.16	Summary	89
4	Laplace Transform	91
4.1	Introduction	91
4.2	Definition of the Laplace Transform	92
4.3	Derivation of Laplace Transforms of Simple Functions	92
4.4	Laplace Transform Theorems	94
4.5	CAD Accuracy Checks: CADAC	97
4.6	Application of the Laplace Transform to Differential Equations	97
4.7	Inverse Transformation	98
4.8	Heaviside Partial-Fraction Expansion Theorems	99
4.9	MATLAB Partial-Fraction Example	106
4.10	Partial-Fraction Shortcuts	107
4.11	Graphical Interpretation of Partial-Fraction Coefficients	109
4.12	Frequency Response from the Pole-Zero Diagram	113
4.13	Location of Poles and Stability	116
4.14	Laplace Transform of the Impulse Function	117
4.15	Second-Order System with Impulse Excitation	119
4.16	Additional Matrix Operations and Properties	120
4.17	Solution of State Equation	126
4.18	Evaluation of the Transfer-Function Matrix	128
4.19	Summary	129
5	System Representation	131
5.1	Introduction	131
5.2	Block Diagrams	131
5.3	Determination of the Overall Transfer Function	136
5.4	Standard Block Diagram Terminology	138
5.5	Position Control System	140
5.6	Simulation Diagrams	144
5.7	Signal Flow Graphs	149
5.8	State Transition Signal Flow Graph	154
5.9	Parallel State Diagrams from Transfer Functions	158
5.10	Diagonalizing the A Matrix	160
5.11	Use of State Transformation for the State Equation Solution	168

5.12	Transforming a Matrix with Complex Eigenvalues	169
5.13	Transforming an A Matrix into Companion Form	172
5.14	Summary	175
6	Control-System Characteristics	176
6.1	Introduction	176
6.2	Routh's Stability Criterion	176
6.3	Mathematical and Physical Forms	182
6.4	Feedback System Types	183
6.5	Analysis of System Types	185
6.6	Example: Type 2 System	190
6.7	Steady-State Error Coefficients	192
6.8	CAD Accuracy Checks: CADAC	196
6.9	Use of Steady-State Error Coefficients	196
6.10	Nonunity-Feedback System	198
6.11	Summary	199
7	Root Locus	200
7.1	Introduction	200
7.2	Plotting Roots of a Characteristic Equation	201
7.3	Qualitative Analysis of the Root Locus	204
7.4	Procedure Outline	207
7.5	Open-Loop Transfer Function	208
7.6	Poles of the Control Ratio $C(s)/R(s)$	209
7.7	Application of the Magnitude and Angle Conditions	211
7.8	Geometrical Properties (Construction Rules)	215
7.9	CAD Accuracy Checks (CADAC)	225
7.10	Examples	225
7.11	Example 1: MATLAB Root Locus	231
7.12	Performance Characteristics	234
7.13	Transport Lag	238
7.14	Synthesis	240
7.15	Summary of Root-Locus Construction Rules for Negative Feedback	241
7.16	Summary	242
8	Frequency Response	244
8.1	Introduction	244
8.2	Correlation of the Sinusoidal and Time Responses	245
8.3	Frequency-Response Curves	246
8.4	Bode Plots (Logarithmic Plots)	247
8.5	General Frequency-Transfer-Function Relationships	249
8.6	Drawing the Bode Plots	250
8.7	Example of Drawing a Bode Plot	256
8.8	System Type and Gain as Related to Log Magnitude Curves	259
8.9	CAD Accuracy Check (CADAC)	262
8.10	Experimental Determination of Transfer Functions	262
8.11	Direct Polar Plots	263

8.12	Summary: Direct Polar Plots	269
8.13	Nyquist's Stability Criterion	270
8.14	Examples of Nyquist's Criterion Using Direct Polar Plot	278
8.15	Nyquist's Stability Criterion Applied to Systems Having Dead Time	281
8.16	Definitions of Phase Margin and Gain Margin and Their Relation to Stability	283
8.17	Stability Characteristics of the Log Magnitude and Phase Diagram	285
8.18	Stability from the Nichols Plot (Log Magnitude–Angle Diagram)	286
8.19	Summary	288
9	Closed-Loop Tracking Performance Based on the Frequency Response	290
9.1	Introduction	290
9.2	Direct Polar Plot	291
9.3	Determination of M_m and ω_m for a Simple Second-Order System	292
9.4	Correlation of Sinusoidal and Time Responses	295
9.5	Constant $M(\omega)$ and $\alpha(\omega)$ Contours of $C(j\omega)/R(j\omega)$ on the Complex Plane (Direct Plot)	296
9.6	Constant $1/M$ and α Contours (Unity Feedback) in the Inverse Polar Plane	303
9.7	Gain Adjustment for a Desired M_m of a Unity-Feedback System: Direct Polar Plot	304
9.8	Constant M and α Curves on the Log Magnitude–Angle Diagram (Nichols Chart)	307
9.9	Generation of MATLAB (1992 Student Version) Bode and Nyquist Plots	309
9.10	Adjustment of Gain by Use of the Log Magnitude–Angle Diagram	312
9.11	Correlation of Pole-Zero Diagram with Frequency and Time Responses	312
9.12	Summary	317
10	Root-Locus Compensation: Design	319
10.1	Introduction to Design	319
10.2	Transient Response: Dominant Complex Poles	321
10.3	Additional Significant Poles	326
10.4	Root-Locus Design Considerations	329
10.5	Reshaping the Root Locus	331
10.6	CAD Accuracy Checks (CADAC)	331
10.7	Ideal Integral Cascade Compensation (PI Controller)	332
10.8	Cascade Lag Compensation Design Using Passive Elements	333
10.9	Ideal Derivative Cascade Compensation (PD Controller)	339
10.10	Lead Compensation Design Using Passive Elements	340
10.11	General Lead-Compensator Design	345
10.12	Lag-Lead Cascade Compensation Design	346
10.13	Comparison of Cascade Compensators	349
10.14	PID Controller	352

10.15	Introduction to Feedback Compensation	353
10.16	Feedback Compensation: Design Procedures	355
10.17	Simplified Rate Feedback Compensation: A Design Approach	355
10.18	Design of Rate Feedback	358
10.19	Design: Feedback of Second Derivative of Output	362
10.20	Results of Feedback Compensation Design	364
10.21	Rate Feedback: Plants with Dominant Complex Poles	364
10.22	Summary	365
11	Frequency-Response Compensation Design	367
11.1	Introduction to Feedback Compensation Design	367
11.2	Selection of a Cascade Compensator	369
11.3	Cascade Lag Compensator	372
11.4	Design Example: Cascade Lag Compensation	375
11.5	Lead Compensator	379
11.6	Design Example: Cascade Lead Compensation	381
11.7	Lag-Lead Compensator	385
11.8	Design Example: Cascade Lag-Lead Compensation	387
11.9	Feedback Compensation Design Using Log Plots	390
11.10	Design Example: Feedback Compensation (Log Plots)	392
11.11	Application Guidelines: Basic Minor-Loop Feedback Compensators	397
11.12	Summary	398
12	Control-Ratio Modeling	401
12.1	Introduction	401
12.2	Modeling a Desired Tracking Control Ratio	402
12.3	Guillemin-Truxal Design Procedure	406
12.4	Introduction to Disturbance Rejection	408
12.5	A Second-Order Disturbance-Rejection Model	409
12.6	Disturbance-Rejection Design Principles for SISO Systems	411
12.7	Disturbance-Rejection Design Example	415
12.8	Disturbance-Rejection Models	418
12.9	Summary	422
13	Design: Closed-Loop Pole-Zero Assignment (State-Variable Feedback)	423
13.1	Introduction	423
13.2	Controllability and Observability	424
13.3	State Feedback for SISO Systems	431
13.4	State-Feedback Design for SISO Systems Using the Control Canonical (Phase-Variables) Form	433
13.5	State-Variable Feedback (Physical Variables)	436
13.6	General Properties of State Feedback (Using Phase Variables)	439
13.7	State-Variable Feedback: Steady-State Error Analysis	442
13.8	Use of Steady-State Error Coefficients	444
13.9	State-Variable Feedback: All-Pole Plant	448

13.10	Plants with Complex Poles	451
13.11	Compensator Containing a Zero	451
13.12	State-Variable Feedback: Pole-Zero Plant	453
13.13	Summary	460
14	Parameter Sensitivity and State Space Trajectories	462
14.1	Introduction	462
14.2	Sensitivity	462
14.3	Sensitivity Analysis	466
14.4	Parameter Sensitivity Examples	472
14.5	Inaccessible States	473
14.6	State-Space Trajectories	477
14.7	Linearization (Jacobian Matrix)	488
14.8	Summary	492
15	Digital Control Systems	493
15.1	Introduction	493
15.2	Sampling	494
15.3	Ideal Sampling	496
15.4	z -Transform Theorems	500
15.5	Synthesis in the z Domain (Direct Method)	500
15.6	The Inverse z Transform	503
15.7	Zero-Order Hold	504
15.8	Limitations	506
15.9	Tustin Transformation	507
15.10	Tustin Transformation Properties	509
15.11	Pseudo-Continuous-Time (PCT) Control System (DIG Method)	512
15.12	Analysis of a Basic (Uncompensated) System	514
15.13	Design of Digital Control Systems	519
15.14	Direct (DIR) Design Technique	520
15.15	Lead Controller (Compensator): DIR Design Method	521
15.16	Lag and Lag-Lead Controllers: DIR Design Method	523
15.17	Digitization (DIG) Design Technique	523
15.18	Summary	526
16	Entire Eigenstructure Assignment for Multivariable Systems	527
16.1	Introduction	527
16.2	Effect of Eigenstructure on Time Response	528
16.3	Entire Eigenstructure Assignment	530
16.4	Examples of Entire Eigenstructure Assignment for Regulators	531
16.5	MATLAB Eigenvectors	537
16.6	Uncontrollable Systems	539
16.7	Tracking Systems	541
16.8	Tracking-System Design Example	543
16.9	MATLAB Example of Tracker Design in Sec. 16.8	546
16.10	Summary	551

17	Design of Tracking Systems Using Output Feedback	554
17.1	Introduction	554
17.2	Output Feedback Tracking System	555
17.3	Block Diagonalization	557
17.4	Analysis of Closed-Loop System Performance	559
17.5	Design Procedure for Regular Plants	562
17.6	Regular System Design Example	563
17.7	Irregular Plant Characteristics	566
17.8	Irregular System Performance	568
17.9	Design of the Measurement Matrix M	569
17.10	Irregular System Design Example	571
17.11	Tracker Simulation	574
17.12	Summary	578
18	Quantitative Feedback Theory (QFT) Technique	580
18.1	Introduction	580
18.2	Frequency Responses with Parameter Variations	582
18.3	Introduction to the QFT Method (Single-Loop System)	584
18.4	Minimum-Phase System Performance Specifications	586
18.5	Multiple-Input Multiple-Output (MIMO) Uncertain Plants	590
18.6	Plant Templates of $P(s)$, $\mathcal{TP}(j\omega_i)$	592
18.7	U -Contour	595
18.8	Tracking Bounds $\text{Lm } \mathbf{B}_R(j\omega)$ on the NC	597
18.9	Disturbance Bounds $\mathbf{B}_D(j\omega_i)$: Case 1 [$d_2(t) = D_o u_{-1}(t)$, $d_1(t) = 0$]	600
18.10	Disturbance Bounds $\mathbf{B}_D(j\omega_i)$: Case 2 [$d_1(t) = D_o u_{-1}(t)$, $d_2(t) = 0$]	605
18.11	The Composite Boundary $\mathbf{B}_o(j\omega_i)$	607
18.12	Shaping of $\mathbf{L}_o(j\omega)$	608
18.13	Guidelines for Shaping $\mathbf{L}_o(j\omega)$	614
18.14	Design of the Prefilter $F(s)$	615
18.15	Basic Design Procedure for a MISO System	617
18.16	Design Example 1	618
18.17	Design Example 2	629
18.18	Template Generation for Unstable Plants	630
18.19	Summary	632
	Appendixes	636
A	Table of Laplace Transform Pairs	636
B	Interactive Computer-Aided Design Programs for Digital and Continuous Control-System Analysis and Synthesis	640
B.1	Introduction	640
B.2	Overview of ICECAP-PC and TOTAL-PC	641
B.3	Overview of MATLAB	645
B.4	QFT CAD Packages	647

xiv CONTENTS

B.5	Computer-Aided Design Accuracy Checks (CADAC)	647
B.6	Other Computer-Aided Design Packages	649
	Problems	651
	Answers to Selected Problems	722
	Index	739