

CONTENT

	Page
List of Tables	vii
Preface	ix
Note on English, Metric, and SI Units of Measurement	1
1. Inspection and Testing for Quality Control	3
2. Installing Lot-by-Lot Inspection	9
3. Basis of Sampling Plans	31
4. Process Inspection with Control Charts	45
5. Control of Variability	59
6. Statistical Basis of Control Charts	69
7. Further Control Charts	87
8. Process Capability and Product Tolerances	105
9. Vendor-Vendee Relations	135
10. Organizational Aspects	147
11. Installing Quality Control	159
12. Analysis of Variance	171
13. Optimizing Processing Through Evolutionary Operation	183
14. Statistical Build-up of Tolerances	189
15. Multiple Tolerance Chains	201
16. Evaluation of Reliability	219
17. Reliability Assurance	239
18. Reliability Design	253
Appendixes	267
Glossary	291
Index	305