

---

# Contents

<b>I</b>	<b>INTRODUCTION</b>	<b>1</b>
<b>1</b>	<b>Ceramic Processes and Products</b>	<b>3</b>
1.1	The Ceramic Industry	3
1.2	Ceramic Processes	4
1.3	Ceramic Products	16
<b>II</b>	<b>CHARACTERISTICS OF CERAMIC SOLIDS</b>	<b>21</b>
<b>2</b>	<b>Structure of Crystals</b>	<b>25</b>
2.1	Atomic Structure	25
2.2	Interatomic Bonds	36
2.3	Atomic Bonding in Solids	41
2.4	Crystal Structures	46
2.5	Grouping of Ions and Pauling's Rules	56
2.6	Oxide Structures	61
2.7	Silicate Structures	70
2.8	The Clay Minerals	77
2.9	Other Structures	80
2.10	Polymorphism	81
<b>3</b>	<b>Structure of Glass</b>	<b>91</b>
3.1	Glass Formation	92
3.2	Models of Glass Structure	95

3.3	The Structure of Oxide Glasses	100	
3.4	Submicrostructural Features of Glasses	110	
3.5	Miscibility Gaps in Oxide Systems	117	
3.6	General Discussion	122	
<b>4</b>	<b>Structural Imperfections</b>		<b>125</b>
4.1	Notation Used for Atomic Defects	126	
4.2	Formulation of Reaction Equations	129	
4.3	Solid Solutions	131	
4.4	Frenkel Disorder	139	
4.5	Schottky Disorder	143	
4.6	Order-Disorder Transformations	145	
4.7	Association of Defects	148	
4.8	Electronic Structure	152	
4.9	Nonstoichiometric Solids	157	
4.10	Dislocations	162	
<b>5</b>	<b>Surfaces, Interfaces, and Grain Boundaries</b>		<b>177</b>
5.1	Surface Tension and Surface Energy	177	
5.2	Curved Surfaces	185	
5.3	Grain Boundaries	188	
5.4	Grain-Boundary Potential and Associated Space Charge	190	
5.5	Boundary Stresses	197	
5.6	Solute Segregation and Phase Separation at and Near Grain Boundaries	200	
5.7	Structure of Surfaces and Interfaces	204	
5.8	Wetting and Phase Distribution	209	
<b>6</b>	<b>Atom Mobility</b>		<b>217</b>
6.1	Diffusion and Fick's Laws	219	
6.2	Diffusion as a Thermally Activated Process	227	
6.3	Nomenclature and Concepts of Atomistic Processes	232	
6.4	Temperature and Impurity Dependence of Diffusion	234	
6.5	Diffusion in Crystalline Oxides	239	
6.6	Dislocation, Boundary, and Surface Diffusion	250	
6.7	Diffusion in Glasses	257	

<b>III</b>	<b>DEVELOPMENT OF MICROSTRUCTURE IN CERAMICS</b>	<b>265</b>
<b>7</b>	<b>Ceramic Phase-Equilibrium Diagrams</b>	<b>269</b>
7.1	Gibb's Phase Rule	270
7.2	One-Component Phase Diagrams	271
7.3	Techniques for Determining Phase-Equilibrium Diagrams	276
7.4	Two-Component Systems	278
7.5	Two-Component Phase Diagrams	284
7.6	Three-Component Phase Diagrams	295
7.7	Phase Composition versus Temperature	301
7.8	The System $\text{Al}_2\text{O}_3\text{-SiO}_2$	304
7.9	The System $\text{MgO-Al}_2\text{O}_3\text{-SiO}_2$	307
7.10	Nonequilibrium Phases	311
<b>8</b>	<b>Phase Transformation, Glass Formation, and Glass-Ceramics</b>	<b>320</b>
8.1	Formal Theory of Transformation Kinetics	321
8.2	Spinodal Decomposition	323
8.3	Nucleation	328
8.4	Crystal Growth	336
8.5	Glass Formation	347
8.6	Composition as a Variable, Heat Flow, and Precipitation from Glasses	351
8.7	Colloidal Colors, Photosensitive Glasses, and Photochromic Glasses	364
8.8	Glass-Ceramic Materials	368
8.9	Phase Separation in Glasses	375
<b>9</b>	<b>Reactions with and between Solids</b>	<b>381</b>
9.1	Kinetics of Heterogeneous Reactions	381
9.2	Reactant Transport through a Planar Boundary Layer	385
9.3	Reactant Transport through a Fluid Phase	402
9.4	Reactant Transport in Particulate Systems	413
9.5	Precipitation in Crystalline Ceramics	430
9.6	Nonisothermal Processes	440

<b>10</b>	<b>Grain Growth, Sintering, and Vitrification</b>	<b>448</b>
10.1	Recrystallization and Grain Growth	449
10.2	Solid-State Sintering	469
10.3	Vitrification	490
10.4	Sintering with a Reactive Liquid	498
10.5	Pressure Sintering and Hot Pressing	501
10.6	Secondary Phenomena	503
10.7	Firing Shrinkage	507
<b>11</b>	<b>Microstructure of Ceramics</b>	<b>516</b>
11.1	Characteristics of Microstructure	516
11.2	Quantitative Analysis	523
11.3	Triaxial Whiteware Compositions	532
11.4	Refractories	540
11.5	Structural Clay Products	549
11.6	Glazes and Enamels	549
11.7	Glasses	552
11.8	Glass-Ceramics	555
11.9	Electrical and Magnetic Ceramics	560
11.10	Abrasives	566
11.11	Cement and Concrete	569
11.12	Some Special Compositions	573
<b>IV</b>	<b>PROPERTIES OF CERAMICS</b>	<b>581</b>
<b>12</b>	<b>Thermal Properties</b>	<b>583</b>
12.1	Introduction	583
12.2	Heat Capacity	586
12.3	Density and Thermal Expansion of Crystals	589
12.4	Density and Thermal Expansion of Glasses	595
12.5	Thermal Expansion of Composite Bodies	603
12.6	Thermal Conduction Processes	612
12.7	Phonon Conductivity of Single-Phase Crystalline Ceramics	615
12.8	Phonon Conductivity of Single-Phase Glasses	624
12.9	Photon Conductivity	627
12.10	Conductivity of Multiphase Ceramics	634

<b>13</b>	<b>Optical Properties</b>	<b>646</b>
13.1	Introduction	646
13.2	Refractive Index and Dispersion	658
13.3	Boundary Reflectance and Surface Gloss	664
13.4	Opacity and Translucency	666
13.5	Absorption and Color	677
13.6	Applications	689
<b>14</b>	<b>Plastic Deformation, Viscous Flow, and Creep</b>	<b>704</b>
14.1	Introduction	704
14.2	Plastic Deformation of Rock Salt Structure Crystals	710
14.3	Plastic Deformation of Fluorite Structure Crystals	727
14.4	Plastic Deformation of $\text{Al}_2\text{O}_3$ Crystals	728
14.5	Creep of Single-Crystal and Polycrystalline Ceramics	734
14.6	Creep of Refractories	747
14.7	Viscous Flow in Liquids and Glasses	755
<b>15</b>	<b>Elasticity, Anelasticity, and Strength</b>	<b>768</b>
15.1	Introduction	768
15.2	Elastic Moduli	773
15.3	Anelasticity	778
15.4	Brittle Fracture and Crack Propagation	783
15.5	Strength and Fracture Surface Work Experience	791
15.6	Static Fatigue	797
15.7	Creep Fracture	807
15.8	Effects of Microstructure	808
<b>16</b>	<b>Thermal and Compositional Stresses</b>	<b>816</b>
16.1	Thermal Expansion and Thermal Stresses	816
16.2	Temperature Gradients and Thermal Stresses	817
16.3	Resistance to Thermal Shock and Thermal Spalling	822
16.4	Thermally Tempered Glass	830
16.5	Annealing	833
16.6	Chemical Strengthening	841
<b>17</b>	<b>Electrical Conductivity</b>	<b>847</b>
17.1	Electrical-Conduction Phenomena	847
17.2	Ionic Conduction in Crystals	852

17.3	Electronic Conduction in Crystals	866	
17.4	Ionic Conduction in Glasses	873	
17.5	Electronic Conduction in Glasses	884	
17.6	Nonstoichiometric and Solute-Controlled Electronic Conduction	888	
17.7	Valency-Controlled Semiconductors	899	
17.8	Mixed Conduction in Poor Conductors	902	
17.9	Polycrystalline Ceramics	904	
	<b>18 Dielectric Properties</b>		<b>913</b>
18.1	Electrical Phenomena	914	
18.2	Dielectric Constants of Crystals and Glasses	931	
18.3	Dielectric Loss Factor for Crystals and Glasses	937	
18.4	Dielectric Conductivity	945	
18.5	Polycrystalline and Polyphase Ceramics	947	
18.6	Dielectric Strength	960	
18.7	Ferroelectric Ceramics	964	
	<b>19 Magnetic Properties</b>		<b>975</b>
19.1	Magnetic Phenomena	975	
19.2	The Origin of Interactions in Ferrimagnetic Materials	988	
19.3	Spinel Ferrites	991	
19.4	Rare Earth Garnets, Orthoferrites, and Ilmenites	998	
19.5	The Hexagonal Ferrites	1001	
19.6	Polycrystalline Ferrites	1006	
	<b>Index</b>		<b>1017</b>