

## CONTENTS

	Page
Part 1 Destructive Methods : Principles and Typical Equipments	
Sectioning Methods	1
Wet and/or Dry Film Meters of Gauges	2
Mesle Chord Method	7
Dial (clock) Gauge Methods	7
Chemical Stripping Methods	11
Chemical Dissolution of the Basis Metal	12
Jet and Drop Methods	13
Immersion and Spot tests	15
Calorimetric Method	16
Electrolytic Stripping (Coulometric) Methods	17
Measurement of Breakdown Voltage	23
Spectrographic Methods	24
Part 2 Non-Destructive Methods : Principles and Typical Equipments	
Dial (Clock) Gauge and Weighing Methods	27
Magnetic Attraction Methods	27
Magnetic Induction Methods	32
Eddy Current Methods	42
Capacitative Methods	49
Thermoelectric Methods	50
Optical Methods	51
Photoelectric Method	55
Radiation Methods	56
Crystal Oscillation	68
Electrical Resistance	68
Part 3 Tables	
Table 1 Chemical solution of Coating : Solutions and Operating Conditions	70
Table 2 Electrolytic Solution of Coatings : Solutions and Operating Conditions	76
Table 3 Guide to Destructive Tests	84
Table 4 Destructive thickness Measuring Instruments	88
Table 5 Guide to Non-Destructive Tests	92
Table 6 Non-destructive Thickness Measuring Instruments	96
Table 7 Standard Specifications	110
Table 8 Names and Address	118
Index	121