

Contents

Introduction	13
2 Properties of Polymeric Melts	19
2.1 Rheological Behavior	19
2.1.1 Viscous Properties of Melts	19
2.1.1.1 Viscosity and Flow Functions	20
2.1.1.2 Mathematical Description of the Pseudoplastic Behavior of Melts	21
2.1.1.3 Influence of Temperature and Pressure on Flow Behavior	26
2.1.2 Determination of Viscous Flow Behavior	33
2.1.3 Viscoelastic Properties of Melts	37
2.2 Thermodynamic Behavior	42
2.2.1 Density	42
2.2.2 Thermal Conductivity	44
2.2.3 Specific Heat Capacity	45
2.2.4 Thermal Diffusivity	45
2.2.5 Specific Enthalpy	46
3 Fundamental Equations for Simple Flows	51
3.1 Flow through a Pipe	52
3.2 Flow through a Slit	55
3.3 Flow through an Annular Gap	58
3.4 Summary of Simple Equations for Dies	61
3.5 Phenomenon of Wall Slip	68
3.5.1 Model Considering the Wall Slip	69
3.5.2 Instability in the Flow Function – Melt Fracture	73
4 Computations of Velocity and Temperature Distributions in Extrusion Dies	77
4.1 Conservation Equations	77
4.1.1 Continuity Equation	77
4.1.2 Momentum Equations	78
4.1.3 Energy Equation	80
4.2 Restrictive Assumptions and Boundary Conditions	82
4.3 Analytical Formulas for the Solution of Conservation Equations	84
4.4 Numerical Solution of Conservation Equations	88
4.4.1 Finite Difference Method (FDM)	89
4.4.2 Finite Element Method (FEM)	92
4.4.3 Comparison of FDM and FEM	95
4.4.4 Examples of Computations Using the Finite Difference Method	98
4.4.5 Examples of Computations Using the Finite Element Method	104
4.5 Considerations of the Viscoelastic Behavior of the Material	108
4.6 Computation of the Extrudate Swelling	111
4.7 Methods for Designing and Optimizing Extrusion Dies	116
4.7.1 Industrial Practice for the Design of Extrusion Dies	116
4.7.2 Optimization Parameters	119
4.7.2.1 Practical Optimization Objectives	119
4.7.2.2 Practical Boundary Conditions and Constraints when Designing Flow Channels	119
4.7.2.3 Independent Parameters during Die Optimization	120
4.7.2.4 Dependent Parameters during Die Optimization and Their Modelling	120
4.7.3 Optimization Methods	122
4.7.3.1 Gradient-free Optimization Methods	123
4.7.3.2 Gradient-based Optimization Methods	126
4.7.3.3 Stochastic Optimization Methods	126
4.7.3.4 Evolutionary Methods	126

4.7.3.5 Treatment of Boundary Conditions

4.7.4 Practical Applications of Optimizations Strategies for the Design of Extrusion Dies

4.7.4.1 Optimization of a Convergent Channel Geometry

4.7.4.2 Optimization of Profile Dies

5 Monoextrusion Dies for Thermoplastics

5.1 Dies with Circular Exit Cross Section

5.1.1 Designs and Applications

5.1.2 Design

5.2 Dies with Slit Exit Cross Section

5.2.1 Designs and Applications

5.2.2 Design

5.2.2.1 Fishtail Manifold

5.2.2.2 Coathanger Manifold

5.2.2.3 Numerical Procedures

5.2.2.4 Considerations for Clam Shelling

5.2.2.5 Unconventional Manifolds

5.2.2.6 Operating Performance of Wide Slit Dies

5.3 Dies with Annular Exit Cross Section

5.3.1 Types

5.3.1.1 Center-fed Mandrel Support Dies

5.3.1.2 Screen Pack Dies

5.3.1.3 Side-fed Mandrel Dies

5.3.1.4 Spiral Mandrel Dies

5.3.2 Applications

5.3.2.1 Pipe Dies

5.3.2.2 Blown Film Dies

5.3.2.3 Dies for the Extrusion of Parisons for Blow Molding

5.3.2.4 Coating Dies

5.3.3 Design

5.3.3.1 Center-fed Mandrel Dies and Screen Pack Dies

5.3.3.2 Side-fed Mandrel Dies

5.3.3.3 Spiral Mandrel Dies

5.3.3.4 Coating Dies

5.4 Formulas for the Computation of the Pressure Loss in the Flow Channel Geometries other than Pipe or Slit

5.5 Dies with Irregular Outlet Geometry (Profile Dies)

5.5.1 Designs and Applications

5.5.2 Design

5.6 Dies for Foamed Semi-finished Products

5.6.1 Dies for Foamed Films and Sheets

5.6.2 Dies for Foamed Profiles

5.7 Special Dies

5.7.1 Dies for Coating of Profiles of Arbitrary Cross Section

5.7.2 Dies for the Production of Profiles with Reinforcing Inserts

5.7.3 Dies for the Production of Nets

5.7.4 Slit Die with Driven Screw for the Production of Slabs

Coextrusion Dies for Thermoplastics

6.1 Designs

6.1.1 Externally Combining Coextrusion Dies

6.1.2 Adapter (Feedblock) Dies

6.1.3 Multi-Manifold Dies

6.2	Applications	241
6.2.1	Film and Sheet Dies	241
6.2.2	Blown Film Dies	242
6.2.3	Dies for the Extrusion of Parisons for Blow Molding	242
6.3	Computations of Flow and Design	243
6.3.1	Computation of Simple Multi-layer Flow with Constant Viscosity.	246
6.3.2	Computation of Coextrusion Flow by the Explicit Finite Difference Method	249
6.3.3	Computation of Velocity and Temperature Fields by the Finite Difference Method	252
6.3.4	Computation of Velocity Fields in Coextrusion Flows by FEM	254
6.4	Instabilities in Multi-layer Flow	256
7	Extrusion Dies for Elastomers	263
7.1	Designs of Dies for the Extrusion of Elastomers	263
7.2	Fundamentals of Design of Extrusion Dies for Elastomers	264
7.2.1	Thermodynamic Material Data	264
7.2.2	Rheological Material Data	265
7.2.3	Computation of Viscous Pressure Losses	267
7.2.3.1	Formulas for Isothermal Computations	268
7.2.3.2	Approaches to Non-isothermal Computations.	270
7.2.4	Estimation of the Peak Temperatures	270
7.2.5	Consideration of the Elastic Behavior of the Material	270
7.3	Design of Distributor Dies for Elastomers	272
7.4	Design of Slotted Discs for Extrusion Dies for Elastomers	273
7.4.1	Computation of Pressure Losses	273
7.4.2	Extrudate Swelling (Die Swell)	276
7.4.3	Simplified Estimations for the Design of a Slotted Disc	279
8	Heating of Extrusion Dies	287
8.1	Types and Applications	287
8.1.1	Heating of Extrusion Dies with Fluids	287
8.1.2	Electrically Heated Extrusion Dies	288
8.1.3	Temperature Control of Extrusion Dies	289
8.2	Thermal Design	290
8.2.1	Criteria and Degrees of Freedom for the Thermal Design	290
8.2.2	Heat Balance at the Extrusion Die	292
8.2.3	Restrictive Assumptions for the Development of a Model	296
8.2.4	Simulation Methods for the Thermal Design	296
9	Mechanical Design of Extrusion Dies	
9.1	Mechanical Design of a Breaker Plate	305
9.2	Mechanical Design of a Die with Axially Symmetrical Flow Channels	310
9.3	Mechanical Design of a Slit Die	317
9.4	General Design Rules	320
9.5	Materials for Extrusion Dies	322
10	Handling, Cleaning and Maintaining Extrusion Dies	329
11	Calibration of Pipes and Profiles	333
11.1	Types and Applications	335
11.1.1	Friction Calibration	335
11.1.2	External Calibration with Compressed Air	335

11.1.3	External Calibration with Vacuum	336
11.1.4	Internal Calibration	340
11.1.5	Precision Extrusion Pullforming (The Technoform Process)	341
11.1.6	Special Process with Movable Calibrators	341
11.2	Thermal Design of Calibration Lines.	342
11.2.1	Analytical Computational Model.	343
11.2.2	Numerical Computational Model.	346
11.2.3	Analogy Model	351
11.2.4	Thermal Boundary Conditions and Material Data	354
11.3	Effect of Cooling on the Quality of the Extrudate.	354
11.4	Mechanical Design of Calibration Lines	355
11.5	Cooling Dies, Process for Production of Solid Bars.	355

Index		361
--------------	--	------------