

CONTENTS

Preface	xiii
List of Symbols	xvii
1 INTRODUCTION	1
1.1 The Economic Role of Manufacturing	4
1.2 Manufacturing as a Technical Activity	5
1.3 Interaction between Design and Manufacturing	7
1.4 Materials in Manufacturing	8
1.5 Scope and Purpose of Book	11
2 MANUFACTURING PROPERTIES OF METALS AND ALLOYS	15
2.1 Pure Metals	15
2.1.1 Melting and Solidification	
2.1.2 Deformation	
2.1.3 Textures (Anisotropy)	
2.1.4 Effect of Grain Size	
2.1.5 Strain Hardening	
2.1.6 Ductility	
2.1.7 Cold Working	
2.1.8 Restoration Processes (Softening)	
2.1.9 Hot Working	
2.2 Alloys	34
2.2.1 Solid Solutions	
2.2.2 Yield-Point Phenomena	
2.2.3 Manufacturing Properties of Two-Phase Structures	
2.2.4 Alloys with Invariant Reactions	
2.2.5 Nonequilibrium Solidification	
2.2.6 Limited Liquid Solubility	
2.2.7 Precipitation Hardening	
2.2.8 Eutectoid Transformation in Steel	
2.3 Multiphase Materials	49
2.3.1 Ternary and Polycomponent Alloys	
2.3.2 Inclusions	
2.3.3 Gases	

2.4	Adhesion	51
2.5	Summary	52
2.5.1	Strength	
2.5.2	Ductility	
2.5.3	Multiphase Materials	
2.5.4	Adhesion	
	Problems	55
3	SOLIDIFICATION PROCESSES	57
3.1	The Metal	57
3.1.1	Melting	
3.1.2	Pouring and Solidification	
3.1.3	Casting Properties	
3.1.4	Casting Alloys	
3.2	Casting Processes	74
3.2.1	Expendable-Mold Casting	
3.2.2	Permanent-Mold Casting	
3.2.3	Centrifugal Casting	
3.3	Finishing Processes	82
3.4	Design for Casting	84
3.5	Crystal Growing	85
3.6	Summary	86
	Problems	87
4	BULK DEFORMATION PROCESSES	91
4.1	Classification of Processes	91
4.2	The Metal	93
4.2.1	Bulk Workability	
4.2.2	Wrought Alloys	
4.3	Forces in Bulk-Deformation Processes	102
4.3.1	The Relevant Flow Stress	
4.3.2	The Effects of Friction	
4.3.3	Inhomogeneous Deformation	
4.3.4	Calculation of Forces	
4.4	Forging	111
4.4.1	Open-Die Forging	
4.4.2	Impression-Die Forging	
4.4.3	Closed-Die Forging	
4.4.4	Forge Rolling and Rotary Swaging	
4.5	Extrusion	126
4.5.1	The Extrusion Process	
4.5.2	Hot Extrusion	
4.5.3	Cold Extrusion	
4.5.4	Hydrostatic Extrusion	
4.5.5	Extrusion Forces	
4.5.6	Process Limitations	
4.6	Forging and Extrusion Equipment	132
4.6.1	Hammers	
4.6.2	Presses	
4.6.3	Upsetters and Cold-Headers	
4.6.4	Tools and Dies	
4.7	Drawing	138
4.7.1	The Drawing Process	
4.7.2	Forces	
4.7.3	Process Limitations	

4.8 Rolling	140
4.8.1 Flat-Rolling 4.8.2 Shape Rolling 4.8.3 Ring Rolling 4.8.4 Transverse Rolling 4.8.5 Calculation of Forces and Power Requirements 4.8.6 Process Limitations	
4.9 Summary	146
Examples	148
Problems	153
5 SHEET-METALWORKING PROCESSES	157
5.1 The Metal	157
5.2 Shearing	158
5.3 Bending	163
5.4 Spinning	168
5.5 Sheet Forming	168
5.5.1 Stretch Forming 5.5.2 Deep Drawing 5.5.3 Combined Stretch- ing-Drawing 5.5.4 Press Forming 5.5.5 Special Operations	
5.6 Sheet-Metalworking Equipment	178
5.7 Summary	179
Problems	180
6 MANUFACTURING PROCESSES FOR POLYMERS	183
6.1 Organic Polymers	186
6.1.1 Thermoplastic Polymers 6.1.2 Thermosetting Polymers 6.1.3 Elastomers 6.1.4 Molding Processes 6.1.5 Thermoforming 6.1.6 Filled and Laminated Polymers 6.1.7 Plastic-Processing Equipment 6.1.8 Process Limitations and Design Aspects	
6.2 Glasses	201
6.2.1 The Structure of Glass 6.2.2 Properties and Manufacture	
6.3 Summary	205
Problems	207
PARTICULATE PROCESSING	209
7.1 Compaction	209
7.1.1 Dry Particulate 7.1.2 Plastic Forming 7.1.3 Slurries	
7.2 Sintering	211
7.3 Hot Compaction	213

7.4 Ceramics	213
7.4.1 Structural Ceramics 7.4.2 Industrial Ceramics	
7.5 Powder-Metallurgy Products	214
7.5.1 The Powder 7.5.2 Pressing of Metal Powders 7.5.3 Sintering	
7.6 Composite Materials	218
7.7 Equipment	219
7.8 Process Limitations and Design Aspects	219
7.9 Atomic Processing	220
7.9.1 Electroforming 7.9.2 Vapor Deposition	
7.10 Summary	222
Problems	223
8 MACHINING	225
8.1 The Metal-Cutting Process	225
8.1.1 Forces in Cutting 8.1.2 Chip Formation 8.1.3 Interactions between Workpiece and Tool	
8.2 The Metal	233
8.2.1 Machinability 8.2.2 Machinable Materials 8.2.3 Free-Machining Alloys 8.2.4 Forces and Energy Requirements	
8.3 Cutting Tools	240
8.3.1 Tool Materials 8.3.2 Tool Construction	
8.4 Methods of Machining a Shape	246
8.4.1 Forming 8.4.2 Generating	
8.5 Single-Point Machining	248
8.5.1 The Tool 8.5.2 Turning 8.5.3 Boring 8.5.4 Facing 8.5.5 Forming 8.5.6 Automatic Lathe 8.5.7 Turret Lathe 8.5.8 Automatic Screw Machines 8.5.9 Shaping and Planing	
8.6 Multipoint Machining	257
8.6.1 Drilling 8.6.2 Milling 8.6.3 Sawing and Filing 8.6.4 Broaching	
8.7 Cutting Conditions and Economy	264
8.7.1 Cutting Speeds and Feeds 8.7.2 Choice of Machine Tool 8.7.3 Cutting Economy	
8.8 Random-Point Machining	271
8.8.1 Abrasive Machining 8.8.2 Abrasives 8.8.3 Bonded Abrasives 8.8.4 Machining with Loose Abrasives	
8.9 Electrical and Chemical Machining	278
8.9.1 Chemical Machining (CM or CHM) 8.9.2 Electrochemical Machining (ECM) 8.9.3 Electrodischarge Machining (EDM) 8.9.4 High-Energy Beam Machining	

8.10 Machining of Polymers and Ceramics	281
8.10.1 Machining of Plastics 8.10.2 Machining of Ceramics	
8.11 Process Limitations and Design Aspects	283
8.12 Summary	284
Examples	
Problems	287
9 JOINING PROCESSES	291
9.1 Mechanical Joining	291
9.2 Solid-State Bonding	292
9.2.1 Cold Welding 9.2.2 Diffusion Bonding 9.2.3 Forge Welding 9.2.4 Friction Welding	
9.3 Liquid-State Welding	295
9.3.1 The Welded Joint 9.3.2 Weldability 9.3.3 Weldable Materials 9.3.4 Resistance Welding 9.3.5 Electric Arc Welding 9.3.6 Thermal Welding 9.3.7 High-Energy Beam Welding	
9.4 Liquid-Solid-State Bonding	311
9.4.1 Brazing 9.4.2 Soldering 9.4.3 Adhesive Joints	
9.5 Joining of Plastics	312
9.6 Hard Facing	313
9.7 Cutting	313
9.8 Design Aspects	313
9.9 Summary	314
Problems	316
10 MANUFACTURING SYSTEMS	319
10.1 Production Characteristics	319
10.2 Mechanization and Automation	321
10.2.1 Mechanization and Automation of Unit Processes 10.2.2 Mech- anization and Automation of Material Movement	
10.3 Assembly	329
10.4 Production Organization	331
10.4.1 Company Organization 10.4.2 Manufacturing Engineering 10.4.3 Plant Layout 10.4.4 Choice of Optimum Manufacturing Methods	
10.5 Quality Control	336
10.6 Summary	337

11	COMPETITIVE ASPECTS OF MANUFACTURING PROCESSES	339
	11.1 Dimensional Accuracy and Surface Finish	340
	11.1.1 Tolerances 11.1.2 Surface Roughness 11.1.3 Shape and Location Deviations 11.1.4 Economic Aspects	
	11.2 Shape and Dimensional Limitations	348
	11.2.1 Shape Limitations 11.2.2 Size Limitations	
	11.3 Manufacturing Costs	350
	11.3.1 Operating Costs (Direct Costs) 11.3.2 Indirect Costs 11.3.3 Fixed Costs	
	11.4 Alternative Processes	360
	11.5 Summary	363
	Example	364
	Problems	366
	APPENDIX A FLOW STRESS DETERMINATION	369
	APPENDIX B CONVERSION FACTORS	373
	Solutions to Selected Problems	375
	Index	377