## 681.12 HUMp V.1

## CONTENTS

Foreword	vii
Introduction	ix
I. Apparatus	11
II. Methods	16
Experiments	
1. To measure a double – ended plain plug gauge	22
2. To measure a gap gauge with slip gauges	25
3. To measure the height of a circular spigot	28
4. To measure a flush – pin depth gauge	31
5. To calibrate a micrometer	33
6. To measure a plain ring gauge	36
7. To measure a taper plug gauge	39
8. To measure a taper ring gauge ( Large diameter )	43
9. To measure a taper ring gauge with balls and depth gauge	47
10. To measure a plug screw gauge	50
11. To check a straight – edge	54
12. To check an engineer 's square	57
B.S.S. Referred to in experiments	60