

**CONTENTS**

Introduction	v
25. To measure the effective diameter of a ring screw gauge using a horizontal comparator or measuring machine	9
26. To set and calibrate an engineer 's block level	14
27. To compare the lengths of two end gauges on an N.P.L. type level comparator	20
28. To measure the included angle of a taper plug gauge using an auto – collimator	26
29. To test a straightedge using an auto – collimator	35
30. To calibrate a dial gauge	43
31. To measure an angular plate gauge using an optical dividing head	48
32. To calibrate a dividing head or table using angle gauges and an auto – collimator	53
33. To calibrate a divided circle using two micro – scopes	61
34. To compare two slip gauges using an optical flat	67
35. To test the flatness of a surface plate using a block level	71
36. To check the involute profile of a spur gear using a dividing head	81
Appendix	87
Bibliography	88