

# Index

- Additives for processing, 121
- Adsorption:
  - BET equation, 21
  - chemical, 21, 127
  - classical isotherms, 22
  - physical, 21, 113, 127
  - polymer molecules, 156, 241
  - specific ions, 136, 138
- Advanced ceramics, 3
- Agglomerates, 38, 61, 85, 215, 264
- Agglomeration, 25, 313
- Aggregates, 33, 38, 50, 62, 85, 452
- Alkoxides, 49, 403
- Alumina, 4, 5, 8, 9, 10, 38, 39, 51, 63, 64, 109, 112, 115, 134, 191, 195, 263, 319, 332, 449
- Annealing, 469
- Antifoaming additive, 180
- Archimedes balance technique, 108
- Aspect ratio, 86
- Atomic adsorption spectrometry, 70
- Atomization, 319, 434, 435
- Attrition milling, 259, 270
  
- Ball milling, 256, 268, 398
- Bancroft rule, 130
- Batching, 277
- Bayer process, 38
- Beneficiation, 12, 36, 253, 255, 298
- Bentonite, 34, 119, 435
- Binders and bonds:
  - admixing, 159
  - burnout, 447
  - cellulose type, 157
  - compositions of common types, 153
  - degree of substitution, 157
  - gelation, 161, 162, 163, 248
  - general effects, 163, 164
  - glass transition temperature, 174, 175
  - glassy state, 174, 175
  - glycols, 158
  - hydraulic type, 168
  - molecular structure, 155, 156, 157, 158
  - plasticizers, 174, 177
  - polymer resins, 165
  - properties of films, 176, 177, 179
  - reaction type, 166, 167
  - rubbery state, 174, 175
  - silicates, 153, 163
  - vinyl type, 155
  - viscosity grade, 161
  - waxes, 158
- Blanking, 429
- Bulk solids handling, 277, 278
  
- Calcining of powder mixtures, 40, 42, 44
- Calcium aluminate cements, 171
- Carbides, 6, 38, 384, 449
- Carter equation, 41
- Casting:
  - compositions, 383
  - defects, 383, 395, 399
  - electrophoretic, 395
  - gelation, 388
  - mechanics, 308, 386, 392
  - molds, 384, 385, 386
  - of monosize particles, 399
  - nonaqueous, 384

- Casting (*Continued*)
  - pressure casting, 393, 394
  - slip casting, 381
  - solid casting, 394
  - tape casting, 395, 396, 397
  - vacuum casting, 393
- Cements, 168
- Ceramic products, 7
- Characterization:
  - in ceramic processing, 14
  - parameters, 62
- Charging of particles, 132, 142
- Chemical analysis, 68, 71
- Chemical vapor deposition, 405
- Chemisorption of water, 127
- Classification, 299
- Clays, 34, 36, 133, 147, 153, 154, 206, 245, 246, 390, 448, 464
- Coagulation, 146, 147, 148, 247, 360, 383, 388
- Coatings, *see* Glazes
- Colloids, 62, 153, 241, 387, 399
- Comminution:
  - anelastic effects, 261
  - Charles equation, 272
  - crushers, 255, 256
  - dispersion of agglomerates, 264, 268, 454
  - efficiency, 272, 274
  - feed size, 257
  - general parameters, 265, 266
  - grinding energy, 261
  - media density and size, 261
  - mills, 255, 256
  - particle fracture, 261, 262
  - particle size effect, 262
  - product size distributions, 270
- Compaction:
  - compressibility, 214
  - direct shear, 210
  - horizontal/vertical stress ratio, 212
  - isostatic, 212, 213
  - Mohr–Coulomb failure law, 211
  - principal stresses, 209
  - shear resistance, 210
  - springback, 214
  - stress path, 209
  - triaxial, 210
  - uniaxial confined, 212, 213
- Compressibility, 214
- Consistency, 200
- Coprecipitation, 48
- Cyclones, 300
- Decals, 433
- Deflocculants, 137, 139, 383, 397, 435
- Deflocculation:
  - DLVO model, 144
  - particle charging, 132, 133, 134
  - steric hindrance, 145, 146
- Density:
  - definitions, 106
  - measurement techniques, 107, 108, 110
  - values for materials, 476, 478
- Dew point, 414
- Dielectric constant of liquids, 125
- Differential thermal analysis, 77, 79, 446
- Dipping, 437
- Direct shear test, 210
- DLVO theory, 144
- Double layer theory, 139
- Double layer thickness, 140
- Drying:
  - controlled humidity drying, 420
  - critical temperature and pressure, 414
  - defects, 418, 419
  - dew point, 414
  - freeze-drying, 53, 423
  - heating, 412
  - infrared, 412, 414
  - latent heat of vaporization, 413
  - mechanisms, 412, 413, 415
  - microwave drying, 412, 414, 421
  - shrinkage, 417, 418
  - slurry drying, 421
  - solvent vaporization, 125
  - spray drying, 51, 317, 423
  - stages, 415, 416
  - techniques, 411
- Dry pressing:
  - compaction stages, 336, 337
  - compositions, 332
  - defects, 348, 349
  - ejection, 342
  - granule deformation, 339, 340
  - other pressing modes, 351
  - powder flow, filling, 335
  - pressing granules, 333
  - pressure transmission, 346
  - springback, 342, 343
  - stages, 329
  - surface roughness, 340, 349
  - tooling, 330, 331, 350
- Effective stress, 202, 228
- Electron microscopy, 74, 75

- Electrophoretic mobility, 141
- Emission spectrometry, 70
- Energy dispersive spectroscopy, 75
- Extrusion:
  - body variables, 366
  - compositions, 359
  - defects, 368, 369, 370
  - die wall effects, 362
  - flow, 361, 364, 370
  - machines, 358
  - mechanics, 360, 362, 363, 364
  - stages, 356
- Feldspar, 14
- Ferrites, 4, 40, 321, 332
- Fettling, 429
- Filtration:
  - equipment, 302
  - parameters, 308, 309
  - theory, 307
- Firing:
  - atmosphere effects, 446, 448, 469
  - binder burnout, 447
  - cooling cycle, 469
  - glazes, 466
  - heating modes, 442, 445
  - heating rate effects, 459
  - kilns, 440
  - presintering processes, 445
  - product support, 442
  - sintering processes, 449
- Flame spraying, 437
- Flash point of liquids, 125
- Flocculants, 152
- Flocculation, 147, 163
- Flow:
  - of bulk solids, 279, 280
  - of pressing granules, 335
- Flow diagram of processing, 13
- Foaming agent, 179
- Forming processes, 327
- Freeze-drying, 53
- Friction, 204, 206, 212, 344, 345
- Gaudin-Schuhmann equation, 101
- Gelation, 161, 162, 248, 388
- Geometric mean size, 98, 103
- Geometric standard deviation, 98, 103
- Glass transition temperature, 174, 343, 375, 462, 469
- Glazes:
  - application, 434, 437
  - firing, 466
- Grain growth:
  - exaggerated grain growth, 456
  - grain growth equations, 454, 455
  - inhibitors, 455, 458
  - regular grain growth, 454, 456
- Granulation:
  - direction granulation, 313
  - spray drying, 317
- Granule characteristics, 319, 320, 324, 336
- Green strength, 216, 217, 344
- Grinding:
  - of particles, *see* Comminution
  - surface grinding, 426
- Guoy-Chapman theory, 139, 146
- Henry constant, 141
- Heteropolar coagulation, 147
- HLB number, 130
- Hofmeister series, 146
- Hot isostatic pressing, 471
- Hot pressing, 470
- Hydraulic cements, 168
- Hydroclones, 300
- Hydrolysis of ions, 136, 137
- Hydrophilic groups, *see* Lyophilic groups
- Hydrophobic groups, *see* Lyophobic groups
- Hydrothermal preparation of powders, 55, 56
- Industrial chemicals, 36
- Industrial minerals, 32
- Infrared adsorption, 72, 412
- Injection molding, 373
- Isoelectric point, 134
- Isostatic pressing, 212, 349
- Jiggering, 371
- Kaolin, 32, 33, 34, 36, 66, 132, 246, 448, 464
- Kelvin equation, 20, 116
- Kilns, 440, 441, 443, 444
- Laminating, 429
- Lamination defect, 399
- Laplace equation, 19
- Laser-assisted size analysis, 90, 91
- Liquids:
  - adsorption on solids, 127
  - capillary effect, 24
  - compositions, 125
  - physical properties, 18, 125, 126, 413
- Log normal distribution function:
  - calculation of mean size, 99
  - definition, 98

- Log normal distribution function (*Continued*)  
 parameters for materials, 100, 191, 193
- Lubricants, 165, 180, 332, 375
- Lubrication:  
 in extrusion, 362, 365  
 in pressing, 342, 343, 344, 347  
 principles, 180, 207
- Lyophilic groups, 128, 129
- Lyophobic groups, 128, 129
- Magnesia, 34, 52
- Materials, *see also* Raw materials  
 characterization, 59  
 compositions, 8, 31, 47
- MBI index, 116, 119
- Mercury intrusion analysis, 111
- Micelles, 130
- Microscopic analysis, 75, 83
- Milling, *see* Comminution
- Mixedness:  
 analysis of, 283, 284  
 homogeneity, 281  
 intensity of segregation, 281  
 microscale, 285  
 parameters, 282, 283  
 random, 281  
 scale of segregation, 281
- Mixing:  
 difficult situations, 295  
 equipment, 286  
 general performance, 293  
 granular materials and powders, 291  
 mechanisms, 285  
 plastic bodies, 291, 357  
 slurries, 286, 398
- Mohr–Coulomb equation, 219
- Montmorillonite, 34
- Nitrides, 6, 38, 54, 384, 458
- Nonaqueous liquids, 126, 359, 384, 397, 422, 430
- Particle concentration processes, 298
- Particle mechanics:  
 contact stress, 202  
 effective stress, 202, 228, 327, 392  
 friction, 204  
 Mohr–Coulomb equation, 211  
 q-p loading diagram, 209  
 strength of agglomerate, 215  
 stresses in powder mass, 208, 209
- Particle packing:  
 Andreasen distribution, 192, 193  
 configurations for packed spheres, 186  
 coordination numbers, 187  
 Dinger–Funk distribution, 194  
 Furnas model, 188, 189, 190  
 hindered packing, 195, 196  
 log normal distributions, 191  
 packing densities, 186, 187, 188, 190, 191, 192, 194, 195, 196, 449  
 particle contacts, 188  
 particles per unit volume, 187  
 pore sizes, 112, 187, 196, 305
- Particles:  
 calculating mean size, 96  
 characteristics, 61  
 charging, 132  
 CLA roughness, 205  
 density, 105  
 shape factors, 86  
 size analysis techniques, 83, 92, 93
- Particle separation processes, 298
- Permeability, 303, 304, 305, 306, 391
- Phase analysis, 71, 73
- Phosphate bonds, 167
- Physical adsorption, 21
- Plastic forming, 355
- Plasticity, 218, 220
- Plasticizers:  
 for organic binders, 174, 177, 332  
 for polymers and waxes, 179, 375
- Plastic pressing, 371
- Point of zero charge, 133
- Poiseuille equation, 24
- Polar groups, 128, 138
- Polyelectrolytes, 137, 383
- Polymers, 165, 166, 375
- Pore pressure, 203
- Pore size analysis, 110, 116, 459
- Portland cement, 169, 170
- Preservatives for binders, 181
- Presintering processes, 445
- Pressing, *see* Dry pressing
- Printing:  
 compositions, 430  
 decals, 433  
 defects, 432  
 pad transfer printing, 433  
 screen printing variables, 430, 431
- Properties for classifying ceramics, 8
- Quartz, 34, 35
- Raw materials:  
 Bayer process, 38

- crude, 31, 32
- industrial inorganic chemicals, 36
- industrial minerals, 32
- kaolin refining, 36
- solid-state reactions, 41
- special inorganic chemicals, 47
- specifications, 63
- Rheology:
  - apparent viscosity, 230
  - behavior of binder solutions, 160, 162, 164, 237, 238
  - behavior of slurries, 239, 240, 242, 243, 244, 247, 318, 383, 388, 398, 435
  - Bingham behavior, 230, 362, 363
  - Casson equation, 231
  - dilatant behavior, 230
  - gel strength, 231, 236, 388
  - laminar flow, 235
  - Newtonian behavior, 229
  - plastic bodies, 220, 221, 222
  - pseudoplastic behavior, 229, 235, 376, 398, 435
  - Reynolds number, 87, 235, 303
  - shear rates in processing, 232
  - shear resistance, 218, 228
  - slippage, 233
  - test methods, 232, 234
  - thixotropic behavior, 231, 236
  - turbulent flow, 235
  - viscosity of liquids, 125, 229
- Roll pressing, 351
- Rosin–Rammler equation, 99
- Scanning electron microscopy, 74
- Schulze–Hardy rule, 146
- Science in ceramic processing, 12
- Screening, 299
- Sedimentation analysis, 87
- Sedimentation density, 148
- Separation processes, 298
- Shear rates in processing, 222
- Shear resistance, 218, 220, 222, 228
- Sieve series, 475
- Sieving techniques, 86
- Sintering:
  - chemical doping, 56
  - definition, 440
  - densification aids, 449, 459, 463
  - of glass:
    - bloating, 462, 463
    - Frenkel equation, 461
    - Mackenzie–Shuttleworth equation, 462
    - slumping, 462
    - of glazes, 466
    - with liquid phase, 463, 464
    - mass transport mechanisms, 451
    - shrinkage, 452, 461, 465, 466
    - in solid state, 449
    - stages, 450
    - of whitewares, 464
  - Sizing of particles, 298
  - Slip casting, 381
  - Slurries, 201, 249
  - Sol-gel forming, 403
  - Sol-gel preparation of powders, 53, 54
  - Solid-state reactions, 41, 42, 43, 44, 56
  - Solid-state sintering:
    - atmosphere effects, 459
    - densification aids, 449, 459
    - inhomogeneous sintering, 452
    - microstructural changes, 450
    - pore mobility, 457
    - stages, 449
    - transport mechanisms, 451
  - Solvent techniques for preparing powder, 51
  - Special inorganic chemicals, 47
  - Specific surface area, 113, 115
  - Spectroscopic analyses, 69
  - Spray drying, 51, 317
  - Spray granulation, 313
  - Spraying, 319, 405, 434
  - Spray pyrolysis, 52
  - Springback, 214, 219
  - Steric hindrance, 145, 196
  - Stokes settling theory, 88
  - Surface analysis, 76
  - Surface finishing, 426
  - Surface roughness, 35, 205
  - Surface tension, 17, 125
    - definition, 17
    - values, 18, 19
  - Surfactants, 128, 129, 264, 332, 397, 435
  - Syneresis, 161
- Talc, 34
- Tape casting:
  - examples of compositions, 397
  - defects, 399
  - process, 397
- Thermochemical analysis, 43, 77, 79, 115, 446
- Thermogravimetric analysis, 79, 446
- Thermophysical analysis, 78, 162, 175, 448
- Titanates, 41, 42, 65
- Tortuosity, 304
- Toughness, 219
- Traditional ceramics, 8, 29

- Van der Waals force, 25
- Vapor phase reaction, 54, 405
- Vibratory milling, 258, 270
- Viscosity, *see also* Rheology
  - aging, 247
  - behavior of liquids, 236
  - behavior of slurries, 242
  - coagulation index, 247
  - gelation effect, 162, 236, 388
  - hydrodynamic shape factor, 239
  - values for liquids, 125, 126, 478
- Washburn equation, 110
- Washing operations, 298, 310
- Water:
  - adsorption on surfaces, 127
  - conductivity, 124
  - properties, 18, 125, 126, 413, 478
  - reagent grade, 126
  - total dissolved solids, 124
- Wetting, 22, 129
- Whiteware, 8, 464
- Young equation, 22
- X-ray diffraction, 73
- Zeta potential, 141, 142, 143, 196
- Zircon, 34
- Zirconia, 34