

Index

- A**
- Acid sizing, neutral and alkaline conditions
 application
 alkyl ketene dimer (AKD) size, 84
 alkyl succinic anhydride (ASA) size, 84–85
 rosin size, 83
 runnability problems, 86
 problems
 defoamers, 112
 foam, 111
 shelf life, 112
 size migration and slip, 111
 size storage, 112
 two sidedness, 110
 product type
 alkyl ketene dimer (AKD), 76–78
 alkyl succinic anhydride (ASA), 78–79
 paraffin wax emulsions, 79–80
 rosin sizes, 74–76
 requirements, 80–83
 sizing product, 74
 synthetic type
 AKD and ASA, 95
 alkalinity, 97–98
 drying temperature, 103–104
 pH, 95–97
 stock temperature, 102–103
 system charge, 98–102
 troubleshooting problems
 deposits, 109–110
 fugitivity, 106–108
 rosin size, 88–95
 size level, 87–88
 slow cure, 105
- AKD. *See* Alkyl ketene dimer sizes
 Alkyl ketene dimer sizes (AKD)
 application, 84
 product type
 anionic trash collector (ATC), 78
 ketene ring reaction, 77
 synthetic, reactive sizing agent, 76
- Alkyl succinic anhydride (ASA)
 application, 84–85
 product type
 fines and filler, 79
 ketene group, 78
- Amorphous silicates, 122–123
 Anionic trash catchers (ATC), 6
 ASA. *See* Alkyl succinic anhydride
- B**
- Biofilm formation
 control methods
 biodispersants and biofilm inhibitors, 20–21
 microbicides usage, 19–20
 oxidising compounds, 20
 system contamination, 18–19
 stages
 base layer, 14
 dislodging into process flow, 16
 extracellular polysaccharides (EPS), 15
 maturation, 15
 surface colonisation, 14
- Britt Dynamic Drainage Jar apparatus, 46
- C**
- Calcium carbonates (CaCO_3), fillers
 chalk, 117
 ground calcium carbonate (GCC), 118
 precipitated calcium carbonate (PCC)
 aragonite, 119
 carbon emissions, 118
 rhombohedral, 119
 scalenohehdral, 120

Canadian Standard Freeness Tester, 45

Colouration

- applications, 201–202
- chemistry, 196–197
- factors affecting choice and performance
 - broke and fixing agents, 203
 - consistency, 202–203
 - filler, 203
 - furnish variations and pulp freeness, 202
 - sheet moisture content, 203–204
 - water hardness, 203
- light wavelength vs. colour, 196
- measurement, 204–205
- primary colours, 195–196
- selection, 200–201
- types
 - acid dyes, 197
 - anionic direct dyes, 198–199
 - basic dyes, 198
 - cationic direct dyes, 199–200
 - cationic polymer dyes and water-insoluble pigments, 200

Control strategies, wet-end papermaking

- ash control, 214
- combined control strategies, 214
- fixative control
 - functions, 212
 - Mütek™, 212
- gas/air control, 214
- multivariable control (MVC), 214–215
- retention aid control, 213

E

Entrained air monitoring

- entrained gas tester (EGT), 65
- paper machine speed, 66

F

Fillers

- amorphous silicates, 122–123
- calcium carbonates (CaCO₃), 117–120
- fundamental characteristics, 124
- kaolin clays, 114–117
- mineral classifications, 123
- particle morphology
 - aggregated fillers, 128–129
 - discrete particles, 127–128
- particle size and size distribution
 - effective barrier properties, 132
 - pigment industry, 129
 - scalenohedral PCC impact, 130
 - sedigraph, 131
 - steepness factor, 129

- pigment brightness, 124–125
- practical considerations, 132–135
- refractive index
 - light-scattering efficiency, 125
- papermaking materials, 126
- scattering and absorption
 - characteristics, 125
- surface area, 132
- talc, 121–122
- titanium dioxide (TiO₂), 120–121

Foam and entrained air management

- air monitoring
 - entrained gas tester (EGT), 65
 - paper machine speed, 66
- application strategies, 69
- creation and stabilisation
 - hydrophilic and hydrophobic ends, 58
 - recycled fibres, 57
 - stock temperature, 58
 - surfactant orientation, 59
 - wet-end additives, 57
- defoamers and antifoams, 56
- destruction
 - bubble coalescence and rupture, 62, 63
 - defoamer or antifoam products, 62
 - non-spherical nature, 60
 - surface foam, 61
 - surfactant stabilised entrained air, 60
- drawbacks of, 54–56
- laboratory foam cell tester, 68
- paper machines and papermaking systems
 - entrained bubbles, 54
 - machine direction (MD) profile
 - variations, 55
- product type
 - active defoamers ingredients, 64
 - performance criteria, 63
- troubleshooting, 70

G

Glyoxalated polyacrylamide resins (GPAM)

- application guidelines
 - creeping and absorbency, impacts, 168
 - pH and alkalinity effects, 167
 - sulphite and free chlorine effects, 168
- basic chemistry and mechanisms, 163–164
- relative cure rate, 164–166

I

- Inorganic deposits, paper system
 - deposition control methods
 - analysis of, 36

- crystallisation process, 34
 - scale inhibitors, 35
 - felts filler accumulation, 36
 - formation of, 31–32
 - Kraft liner machines and pulp mill systems, 33
 - NSSC pulping process, 33
 - organic or microbiological deposit, filler, 36
 - scale deposits, 32–34
 - TMP refiners and sulphite mills, 33
- K**
- Kaolin clays
 - delaminated, 116
 - fibre extension, 115
 - hexagonal plates, 115
 - papermaking fillers, 114
- M**
- Microbiological deposits, paper system
 - activity measurements
 - analytical methods, 16–17
 - biological methods, 17
 - physical methods, 16
 - biofilm formation
 - base layer, 14
 - biodispersants and biofilm inhibitors, 20–21
 - dislodging process flow, 16
 - extracellular polysaccharides (EPS), 15
 - maturation, 15
 - microbicides usage, 19–20
 - oxidising compounds, 20
 - surface colonisation, 14
 - system contamination, 18–19
 - Clark sensor, 17
 - micro-organisms
 - bacterial microphotographs, 11
 - growth of, 12–14
 - Mütekt DFR-04 drainage retention freeness tester, 48
 - Mütekt™ measuring charge, 209, 213, 214, 220
- N**
- Neutral pH papermaking conditions. *See* Wet-strengthening
- O**
- Online monitoring and control, wet-end papermaking
 - applications
 - board, 219–220
 - fine paper, 215–217
 - newsprint, 217
 - specialty paper and tissue, 218–219
 - charge measuring principles, 209
 - control strategies
 - ash control, 214
 - combined control strategies, 214
 - fixative control, 212–213
 - gas/air control, 214
 - multivariable control (MVC), 214–215
 - Mütekt™ PCD-03 and Mütekt™ SZP-06, 214
 - retention aid control, 213
 - pulp suspension and measuring parameters, 208–209
 - wet-end charge surveys
 - control chemicals, 210
 - paper machine, 210–212
 - Organic deposits, water-insoluble components
 - additives, 23
 - analysis of, 23–24
 - deposition
 - ageing of wood, 27
 - colloidal material retention, 28
 - colloidal stability maximisation, 29–30
 - depositability minimisation, 28–29
 - mechanisms, 24–25
 - organic material content minimisation, 26–27
 - parameters in, 26
 - surface affinity minimisation, 30–31
 - washing operation, 27
 - gas chromatography (GC) methods, 24
 - natural wood extractives, 21–22
 - physical form, 24
 - stickies, inks and white pitch, 22–23
 - styrene butadiene rubber (SBR) latex, 21
- P**
- Paper chemistry
 - acid sizing, neutral and alkaline conditions application, 80–86
 - problems, 110–112
 - product type, 74–80
 - sizing product, 74
 - synthetic, 95–104
 - troubleshooting problems, 87–110
 - biofilm formation, 14–16, 18–21
 - colouration
 - application, 201–202
 - chemistry, 196–197
 - colourant selection, 200–201

Paper chemistry (*cont.*)

- factors affecting choice and performance, 202–204
 - light wavelength vs. colour, 196
 - measurement, 204–205
 - primary colours, 195–196
 - types, 197–200
- entrained air monitoring, 65–67
- fillers
 - amorphous silicates, 122–123
 - calcium carbonates (CaCO_3), 117–120
 - fundamental filler characteristics, 124
 - kaolin clays, 114–117
 - mineral classifications, 123
 - particle morphology, 127–129
 - particle size and size distribution, 129–132
 - pigment brightness, 124–125
 - refractive index, 125–126
 - surface area, 132
 - talc, 121–122
 - titanium dioxide (TiO_2), 120–121
- foam and entrained air management
 - creation and stabilisation, 57–59
 - destruction, 59–63
 - drawbacks of, 54–56
 - product type, 63–64
- glyoxalated polyacrylamide resins (GPAM)
 - application guidelines, 167–168
 - basic chemistry and mechanisms, 163–164
 - relative cure rate, 164–166
- online monitoring and control
 - applications, 215–220
 - charge measuring principles, 209
 - control strategies, 212–215
 - pulp suspension and measuring parameters, 208–209
 - wet-end charge surveys, 210–212
- paper productivity and quality
 - Clark sensor, 17
 - gas chromatography (GC) methods, 24
 - Kraft liner machines and pulp mill systems, 33
 - NSSC pulping process, 33
 - TMP refiners and sulphite mills, 33
 - water-soluble components, 36–37
- polyaminopolyamide-epichlorohydrin resins (PAE)
 - basic chemistry and classification, 149–151
 - chemical additives, 160–161
 - mechanisms, 151–153

- technology, 161–162
- polyvinylamine resins (PVAm), 168–169
- retention and drainage systems
 - Britt Dynamic Drainage Jar apparatus, 46
 - Canadian Standard Freeness Tester, 44
 - components of, 41–43
 - evaluation methods, 44–48
 - flocculated and unflocculated stocks, 40–41
 - limiting factors and detrimental substances, 48–51
 - Mütek DFR-04, 48
 - selection criteria, 43–44
 - troubleshooting, 51–52
- synthetic polymers
 - methods, 142–144
 - polyacrylamides, 137
 - refining, 138–139
 - resins benefits, 138
 - synthetic resin types, 139–141
 - trouble shooting, 144–146
- wet-end
 - chemical performance, 3–4
 - dry and wet strength resins, 4–5
- Paper colouration. *See* Colouration
- Papermaking process
 - drainage and drying, 134
 - filler interactions
 - Kubelka–Munk theory, 132
 - optical scatter characteristics, 133
 - point of addition, 134–135
 - potential interactions, 135
 - retention, 133
- Paper productivity and quality
 - inorganic deposits
 - deposition control methods, 34–36
 - felts filler accumulation, 36
 - formation of, 31–32
 - Kraft liner machines and pulp mill systems, 33
 - NSSC pulping process, 33
 - organic or microbiological deposit, filler, 36
 - scale deposits, 32–34
 - TMP refiners and sulphite mills, 33
 - microbiological deposits
 - activity measurements, 16–17
 - biofilm formation, 14–16, 18–21
 - Clark sensor, 17
 - micro-organisms, 11–14
 - organic deposits, water-insoluble
 - components
 - additives, 23
 - analysis of, 23–24

- deposition, 25–31
 - gas chromatography (GC) methods, 24
 - natural wood extractives, 21–22
 - physical form, 24
 - stickies, inks and white pitch, 22–23
 - styrene butadiene rubber (SBR)
 - latex, 21
 - polymerisation, 37
 - surface quality
 - headbox cleaning, 9
 - limitations, 8
 - papermaking process, 7
 - water-soluble components, 36–37
 - Poly(N-vinylformamide) (PNVF), 141
 - Polyaminopolyamide-epichlorohydrin resins (PAE)
 - application guidelines
 - additional polymers, 158–160
 - factors affecting reaction, 156
 - factors affecting retention, 153–156
 - handling, 153
 - water quality, 156–157
 - basic chemistry and classification
 - dichloropropanol (DCP) and chloropropanol (CPD), 150–151
 - manufacturing, 149–150
 - chemical additives
 - absorbency aids and sizing agents, 161
 - dyes and optical brightening agents, 160
 - softeners and de-bonders, 160–161
 - mechanisms
 - preservation, 151, 153
 - reinforcement, 153
 - technology, 161–162
 - Polyvinylamine resins (PVAm), 168–169
 - Pulp suspension and measuring parameters, 208–209
- R**
- Retention and drainage systems
 - ash retention, 47
 - components, 41–43
 - development, 43
 - evaluation methods
 - ash retention, 47
 - Britt Dynamic Drainage Jar apparatus, 46
 - Canadian Standard Freeness Tester, 44
 - combined systems, 47–48
 - free drainage, 44–46
 - Mütek DFR-04, 48
 - vacuum drainage, 47
 - flocculated and unflocculated stocks, 40–41
 - limiting factors and detrimental substances
 - grades variability, wet-end paper, 48–51
 - paper machine, 51
 - sheet formation and defects, 51
 - stock approach flow, 48
 - paper machine and system chemistry
 - factors, 39
 - paper machine configuration, 44
 - selection criteria, 43–44
 - troubleshooting, 51–52
 - zeta potential, 50
 - Rosin sizes
 - aluminium rosinate, 75
 - application, 83
 - deposits, 109
 - fugitivity, 106
 - lack of sizing
 - alkalinity, 90–91
 - anionic trash, 91–92
 - drying temperature, 93–95
 - pH, 88–90
 - stock temperature, 92–93
 - non-reactive product, 74
 - polyaluminium chloride (PAC), 76
 - product type, 74
 - slow cure, 105
- S**
- Sizing agents. *See* Acid sizing, neutral and alkaline conditions
 - Synthetic polymers
 - methods
 - dosages, 143–144
 - optimum points, 142–143
 - polyacrylamide products, 142
 - polyacrylamides, 137
 - refining, 138–139
 - resins benefits, 138
 - synthetic resin types, 139–141
 - trouble shooting
 - charge balance loss, 145–146
 - sheet formation, 145
 - strength loss, 144–145
 - Synthetic resin
 - benefits, 138
 - general effects, 140
 - glyoxylated resin, 141
 - polyvinylamine strength additives, 139
 - types, 139–141
- T**
- Talc, 121–122
 - Titanium dioxide (TiO₂), 120–121

Troubleshooting sizing problems

deposits

- rosin, 109
- synthetic, 109–110

fugitivity

- rosin, 106
- synthetic, 106–108

lack of sizing

- rosin size, 88–95
- size level, 87–88
- synthetic size, 95–104

slow cure, 105

W

Wet-end charge surveys

- control chemicals, 210
- paper machine, 210–212

Wet-end paper chemistry

chemical performance

- chemical compounds, 4
- sizing, 3–4

chemical process, 2

deposit control, 2

dry and wet strength resins, 4–5

dyeing, 6

fillers, 4

foam, 3

measurement and control, 6

pulp production, 1

retention, drainage and formation, 3

wet-end starch, 5

Wet-strengthening

definition, 147–148

glyoxalated polyacrylamide resins (GPAM)

- application guidelines, 166–168
- basic chemistry and mechanisms, 163–164
- relative cure rate, 164–166

history, 148–149

polyaminopolyamide-epichlorohydrin resins (PAE)

- additional polymers, 158–160
- basic chemistry and classification, 149–151
- chemical additives, 160–161
- chloride ion induced corrosion, 153
- factors affecting reaction, 156
- factors affecting retention, 153–156
- handling, 153
- mechanisms, 151–153
- poor retention consequences, 155–156
- TCF and ECF bleaching, 154
- technology, 161–162
- water quality, 156–157

polyvinylamine resins (PVAm), 168–169