

CONTENTS

Preface	
Plenary Lectures	
Trend in R & D on Corrosion in Japan	17
Microstructural Design for Improved Corrosion Resistance of Advanced Structural Materials Gareth Thomas	26
Co-Deposited Chromium-Aluminide Coatings and Their High-Temperature Corrosion Resistance	43
GROUP A : BASIC APPROACH TO CURRENT PROBLEMS	
The Stress Corrosion Cracking of Copper and Copper Base Alloys	51
Corrosion Failure of High Strength Pre-Stressing Bars	61
A Study on the Behaviour of Hydrogen Induced Cracking of A3 Steel Weldment In the Acid Solutions	68
An Application of Spi Technique for Studing Strain Distribution at Crack Tip	74
The Influence of H ⁺ and Cl ⁻ on SCC of 304 SS IN HCl+ Nacl at Room Temperature	78
CO2 Corrosion of Carbon Steel in Polymer Drilling Fluid	81
Synthesis of Si and Y-Si Thin Films by Ibed to Improve the Oxidation-Resistance of 304 Stainless Steel	84
Influence of Ce Implantation on the Oxidation Behavior of Ni 20 Cr Alloy	91
Evaluation of Soil Corrosivity by Fuzzy Clustering Technique	96
Automatic Construction of Chemical Potential Diagrams and Application to Metallic Corrosion	98
Localized Corrosion of Copper in Wet Organic Acid Vapor	105
Some Recent Developments in the Study of High Temperature Corrosion	110
Corrosion Resistance of High Nitrogen Stainless Steels	115
The Corrosion Performance of Epoxy-Based and Chlorinated Rubber Coatings in Arabian Gulf Seawater	121
Managing Corrosion Monitoring and Inspection Engineering Activities	127
Industrial coatings : Past, Present and Future Developments (Towards “Green” Barriers Between Aggressive Environments and Reactive Metal Surfaces)	136
Cracking Experience in Lpg Storage Vessels	145
Potential Fluctuation During Early Stage of Stress Corrosion Cracking of Type 304 Stainless Steel in Chloride Solution	159

GROUP B : PRACTICAL APPROACH TO CURRENT PROBLEMS

The Corrosion Behavior of 20 Boiler Steel in the Dilute Industrial Solution Containing Polypropylene Carbonate	165
A Study on the Corrosion of 316 L Stainless Steel in the Media of High Pressure Carbamate Condenser	170
Environment Sensitive Fracture Behavior of Reactor Pressure Vessel Steel A 508 in High Temperature Water	181
The Corrosion and Repair of the High Pressure Carbamate Condenser	190
Factors Influencing Hydrogen Induced Disbonding in Hydrogenation Reactors	197
A Case Study of Hydrogen Embrittlement of Titanium Heat Exchanger Tubes in Alkaline Environment	205
Deaeration as a Preventive Method Using Gas Separating Membrane for Water Supply Systems	208
Filiform Corrosion on Alloy 42 Leadframes	215
Corrosion of Underground Pipes (Pvc, Fiberglass-Resin, Asbestos-Cement, Cast Iron, Ductile Cast Iron, Steel) – A Grave Environmental Concern	221
Study on Atmospheric Corrosion in the Philippines Series I : The Effect of Angle of Inclination/Rack Orientation	229
Study on Atmospheric Corrosion in the Philippines Series II : Nationwide Survey of Atmospheric Corrosivity	231
New Aspects of Filiform Corrosion on Marine Iron	237
Characterization of Organic-Coated Steel Plates in 5% NaCl Solution	245
Asean-Japan Project on Atmospheric Corrosion : Organic Coatings	253

GROUP C : CORROSION PREVENTION AND CONTROL

Mild Steel Corrosion in Aqueous Media and Its Inhibition in the Presence of Sodium Propionate	269
Influence of Bicarbonate Ions on the Stability of Copper Oxides and Copper Pitting Corrosion	274
Reduction of Crack Corrosion by Reduction of Local ... By Shape Modification of Welded Parts	279
Deterioration and Thickness Databases of Anticorrosive Paint Coating Films	285
Use of AC Impedance Technique for Evaluating Corrosion Resistance of High Temperature Protective Coatings	289
Corrosion Monitoring of Bottom Plate of Fuel Tanks in Service	295
Metallurgical Effects on the Electrochemical Behavior of A 516 Steel Weldment	300
Effect of Phosphorus on the Electrochemical Behavior of Electroless Ni-P Deposits in 3.5 WT% NaCl Solutions	307
A Study of the Performance of Anti-Rust Paints on Carbon and Atmospheric Corrosion Resistant Steels	313
Condenser Retrofitting Recent Experience of Welded Ferritic Stainless Steel Tubes in Thailand	317
Behavior of a Duplex Stainless Steel Exchanger in Chemical Industry	323
Choice of Stainless Steel Grades in Contact With Chlorinated Water	329
Corrosion Prevention of Stainless Steel in Food Industry : Cleaning and Maintenance	334

Statistical Failure Mode of The Steel Plates in wet H ₂ S Environment	340
Study of Photodegradation of Paint Films Using FTIR	347
Evaluation of Degradation of Centrifugally Cast Furnace Tube in the Petrochemical Plant	352
Super High-Build Epoxy Coating System	358