

CONTENTS

	Page
Introduction	1
Water Pollution Regulations	1
Lining Materials Investigated	2
Compacted Earth Linings	2
Flexible Membrane Linings	2
Hard-Surface Linings	3
Soil Sealants	3
Conclusions	4
Field investigation	4
Laboratory Investigation	5
Initial Investigations	6
Roswell, New Mexico	6
Webster, South Dakota	6
Dalpra Farm	6
Field Installation	6
General	6
Monitoring system for Seepage and Evaporation Measurements	10
Field Test results	12
General	12
Effectiveness of lining Materials	12
Evaluation of Seepage Measurements	15
Laboratory Investigations	21
Laboratory Test Results	21
Soil Testing	21
Soil Sealants	21
Flexible Membrane Linings	22
Asphaltic Concrete	22
Soil-Cement	23
Spray-applied Liquid Asphalt	23
Recommendations	23
General	23
Lining Materials	23
Seepage Monitoring for Brine Disposal Ponds	25
Future Field Tests	29
References	30
Materials Listing	31
Appendix I – Summary of Field Seepage Measurements	33
Appendix II – Laboratory Test Results	45
Appendix III – construction of Test Ponds	95
Appendix IV – Laboratory Test Methods	101